

Map ID  
Direction  
Distance  
Elevation

MAP FINDINGS

EDR ID Number  
EPA ID Number

DL560  
NW  
1/2-1  
0.849 mi.  
4484 ft.

VS# 3239  
BAY 44TH/CROPSY AVE  
BROOKLYN, NY

Site 3 of 3 in cluster DL

NY Spills S106968208  
N/A

Relative:  
Higher

Actual:  
9 ft.

SPILLS:

Name: VS# 3239  
Address: BAY 44TH/CROPSY AVE  
City,State,Zip: BROOKLYN, NY  
Spill Number/Closed Date: 0502289 / 2006-01-06  
Facility ID: 0502289  
Facility Type: ER  
DER Facility ID: 292889  
Site ID: 346622  
DEC Region: 2  
Spill Cause: Unknown  
Spill Class: C4  
SWIS: 2401  
Spill Date: 2005-05-25

Investigator: SKARAKHA  
Referred To: Not reported  
Reported to Dept: 2005-05-26  
CID: 444  
Water Affected: Not reported  
Spill Source: Unknown  
Spill Notifier: Responsible Party  
Cleanup Ceased: Not reported  
Cleanup Meets Std: False  
Last Inspection: Not reported  
Recommended Penalty: False  
UST Trust: False  
Remediation Phase: 0  
Date Entered In Computer: 2005-05-26  
Spill Record Last Update: 2006-01-06  
Spiller Name: Not reported  
Spiller Company: Not reported  
Spiller Address: 66 8TH ST  
Spiller Company: 001  
Contact Name: ERT DESK MIKE DAUGHTERY  
DEC Memo:

"e2mis no 158781 KEN TYLER FOUND APPROX. 1GAL OF UNKNOWN OIL ON APPROX. 20 GAL'S OF WATER. NO SEWERS OR WATERWAYS APPEAR TO BE AFFECTED. THE SPILL APPEARS TO BE CONTAINED. NO PUMP. NO SUMP. OWNER OF SUBSTANCES IS UNKNOWN. NO KNOWN SUBSTANTIAL CRACKS IN STRUCTURE. ENVIR. TAG# 31427 PLACED. 1 LIQ. SAMPLE TO BE TAKEN WHEN SAFE TO DO SO FROM SPILL. UPDATE 25-MAY-2005 19:10 HRS. BQ/E DEPT. MECHA K.DAVIS EMP# 16852 REPORTS: THERE IS APPROX. 500 GALS OF WATER IN THIS STRUCTURE. UNIT WAS PRESSURE TESTED & PASSED AT 7lbs. THE OIL LEVEL IS 25. Lab Sequence Number: 05-04961-001 - Aroclor 1260 < 1.0 ppm "

Remarks: "on 20 gallons of water: coming off 24 hour clock due to cars parked in the way: coned # 158781: no to 5 questions"

All Materials:

Site ID: 346622  
Operable Unit ID: 1104387  
Operable Unit: 01  
Material ID: 584570  
Material Code: 0066A  
Material Name: unknown petroleum  
Case No.: Not reported

Map ID  
Direction  
Distance  
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number  
EPA ID Number

Material FA:	Petroleum
Quantity:	1.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported